

Release Notes

Macintosh driver version 1.1.0-3

1. New Features

a. The following new features were implemented in this release of the driver.

New Feature Summary	Feature ID
The upper right cog menu option to pair a new wireless device to a	18
USB dongle is now greyed out unless a USB wireless dongle is	
attached to the system.	
Updated text in dialog for pairing a new wireless device to a USB	8
wireless dongle.	
In the settings panel, highlight the Set button in the Quick Keys image	20
for the Set the cursor is hovering over.	
In a multiple display environment always present the settings panel	24
on the current active display.	
Added ability to import settings from a previous version of the driver.	58
Improved visibility of the 'gear" icon in the settings panel.	46
Added tumble function for Maya, Zbrush, Substance Painter and	61
Fusion 360.	
Added new icon for driver uninstaller.	
In the wireless pairing tool, added ability to clear a single pairing to a	
wireless device.	
Added ability to save user settings during driver uninstallation.	
Added a confirmation dialog when importing settings.	



2. Defect Fixes

a. The following defects were fixed in this release of the driver.

Defect Summary	Defect ID
Improved wording of prompt to save preferences when uninstalling	1607
driver.	
When the settings panel is opened it is too low on the display. This	1606
position has been adjusted so that the entire settings panel is always	
seen on the active display.	
Intermittent issues with wireless pairing a new tablet or Quick Keys	1600
to a dongle for the first time.	
Issue when importing a preferences file with more than 10 custom	1621
applications included.	
Issue in the setup wizard where 2 Quick Keys are being displays when	1619
only 1 Quick Keys is attached to the system.	
Issue with double clicking on files to open them.	1613
Issues with device not showing up in settings panel when first	1581
connecting to a new wireless dongle.	
The dialog for connected a new wireless device to a dongle is not	1580
being displayed correctly.	
When pairing a new wireless to a dongle the initial tablet to display	1579
mapping is not correct.	
When clicking on the dongle pairing option, the cursor jumps to the	1577
upper left corner of the display.	
Issue in multiple monitor environment where the tablet to display	1558
mapping is reset when waking the system from sleep.	
Unable to open some driver links to website content.	1573

3. Known Issues

a. The following are known issues in the driver and workaround if one exists.

Known Issue Summary	Workaround (if one exists)	Defect ID
No known serious issues at this time.		