

Release Notes

Macintosh driver version 1.2.1-38

1. Defect Fixes

- a. The following defects were the main defects reported by customers and were fixed in this release of the driver.

Defect Summary
Modifier keys not being released in multiple applications.
Unable to drag and drop items to the system Dock in the Portion Mapping mode.
When drawing a line in Clip Studio Painter, a dot appears at the end of the line.

2. Known Issues

- a. The following are known issues in the driver and workaround if one exists.

Known Issue Summary	Workaround (if one exists)
No known serious issues at this time.	